Ref #	Hits	Search Query	DBs	Default Operat or	Plural s	Time Stamp
L3	6093	((fasten\$4 screw nut bolt rivet) near4 (measur\$5 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L4	102601	((stress strain load force pressure) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L5	1389	3 and 4	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:11
L6	50152	((stress strain load force tension) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L7	980	3 and 6	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L8	49	7 and ((thermo\$9 temperature) near4 (measur\$5 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:16
L9	1	"4550255".PN.	USPAT; USOCR	OR	OFF	2005/06/17 09:45
L10	1	"4806292".PN.	USPAT; USOCR	OR	OFF	2005/06/17 09:45
S1	3985	(((two "2" second pair double couple) near3 plate) near4 (fasten\$4 screw nut bolt rivet)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:05
S2	346	S1 and seal\$4.clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:06
S3	0	S2 and 73/761.ccls.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:33

S4	15	S2 and ((stress strain load force pressure temperature) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:11
S5	15	S2 and ((stress strain load force pressure tension temperature) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:09
S6	2	S4 and tension	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:13
S7	2	S4 and tension.clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:08
S8	0	S6 and temperature	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:14
S 9	9	S5 and temperature	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:14
S10	75	S1 and ((stress strain load force pressure tension temperature) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:33
S11	4	S1 and 73/761.ccls.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/16 12:34
S12	1	"4294122".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:36
S13	1	"4899591".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:19
S14	1	"5386733".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:38
S15	1	"5388463".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:38

016		#5200654# DNI	LIODATE	OD	OFF	0005/06/16
S16	1	"5392654".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:38
S17	1	"5437525".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:40
S18	1	"5461923".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:41
S19	1	"5691815".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:41
S20	1	"5721380".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:41
S21	1	"5721380".PN.	USPAT, USOCR	OR	OFF	2005/06/16 12:42
S22	1	"6009759".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:42
S23	1	"4899591".PN.	USPAT; USOCR	OR	OFF	2005/06/16 12:42
S24	. 2	"2287950".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:16
S25	2	"2379800".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:16
S26	2	"2503141".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:17
S27	2	"2600029".PN.	USPAT; USOCR	OR	OFF	2005/06/16 14:17

C20	50	(2201077 2206100	LICDAT	OB	OFF	2005/06/16
S28	52	("3201977" "3306100"	USPAT;	OR	OFF	2005/06/16
		"3307393" "3308476"	USOCR			14:25
		"3541844" "3650016"				
		"3759090" "3810385"				·
		"3812709" "3812758"				
		"3822587" "3823639"				
		"3908508" "3918294"				
		"3924444" "3930405"				
		"3943819" "3969810"				
]		"3969960" "3975948"				
		"3987668" "4014208"		İ		
		"4015464" "4062227"				
		"4117731" "4121467"				
		"4127788" "4144428"			İ	
		"4294122" "4339683"				
		"4344216" "4363242"				
		"4402222" "4413518"				
1		"4423634" "4445360"				
		"4471657" "4565940"				
		"4567766" "4569229"				
		"4584676" "4601207"				
		"4602511" "4633122"				
		"4676109" "4760740").pn.				
		1 4070109 4700740 J.pii.				
S29	14	S28 and temperature	USPAT;	OR	OFF	2005/06/16
			USOCR			14:25

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4	(("4,483,449") or ("4,845,470")). PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/17 10:22
L2	2	("6761073").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/06/17 10:45
L3	12205	heat\$5 near4 (second upper higher another) near3 (temperature).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2005/06/17 10:55
L4	4	3 and fastener near3 (tension load force stress strain).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/17 10:50
L5	8	3 and (screw rivet bolt nut fastener) near3 (tension load force stress strain).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/17 10:52
L6	98	heat\$3 near4 (second upper higher another) near3 (temperature) near6 (screw rivet bolt nut fastener)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON ·	2005/06/17 10:59
L7	27	6 and seal\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2005/06/17 10:59
L8	41	6 and (adhes\$4 seal\$3 glue)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/17 11:00

Ref #	Hits	Search Query	DBs	Default Operat or	Plural s	Time Stamp
L3	6093	((fasten\$4 screw nut bolt rivet) near4 (measur\$5 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF .	2005/06/17 09:12
L4	102601	((stress strain load force pressure) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)) clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L5	1389	3 and 4	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:11
L6	50152	((stress strain load force tension) near4 (measur\$4 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)) clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L7	980	3 and 6	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:12
L8	49	7 and ((thermo\$9 temperature) near4 (measur\$5 calculat\$5 indicat\$5 sens\$4 detect\$4 transducer cell gage gauge)). clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 09:16
L9	· 1	"4550255".PN.	USPAT; USOCR	OR	OFF	2005/06/17 09:45
L10	1	"4806292".PN.	USPAT; USOCR	OR	OFF	2005/06/17 09:45
L11	11726	heat\$5 near4 (second upper higher another) near3 (temperature).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:07
L12	2	11 and fastener near3 (tension load force stress strain).clm.	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:06
L13	46	heat\$5 near4 (second upper higher another) near3 (temperature) near6 (screw rivet bolt nut fastener)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:07

L14	15	13 and seal\$3	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:07
L15	25	13 and (adhesi\$4 seal\$3 glue)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/06/17 11:08